

We have replaced "Down Arrow" to "F5" suffix after reading a tag with new firmware.  
(RD200\_LF\_V0181\_20140210\_F5.SYB)  
Please upgrade attached firmware and select "Add Down Arrow" to test.

